## Oil Field Environmental Incident Summary

**Responsible Party:** WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: BARTLESON 44-1H CTB

Field Name: SANISH Well File #:

Date Incident:3/8/2015Time Incident:13:00Facility ID Number:216068-01County:MOUNTRAILTwp:152Rng:93Sec:1Qtr:SE SE

**Location Description:** 

Submitted By: Brian Wurm Received By:

Contact Person: Brian Wurm

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 1 Barrels 1 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None noted

Areal Extent:

Tuesday, March 24, 2015 Page 1 of 2

## Potential Environmental Impacts:

None noted

## Action Taken or Planned:

Valve was tightened to stop further release. A vac truck was brought in and picked up all free liquids and impacted material

Wastes Disposal Location: Impacted material will be taken to Secure Disposal facility

Agencies Involved:

## **Updates**

Date: 3/9/2015 Status: Reviewed; O&G Lead Staff: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Tuesday, March 24, 2015 Page 2 of 2